



Attorney Docket No. 121.1002D

co/c

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Etsuko HAYASHI, et al.

Application No.: 10/624,568

ATTENTION

Confirmation No.: 6610

CERTIFICATE OF CORRECTION

Filed: July 23, 2003

BRANCH

**Certificate**

U.S. Patent No.: 6,891,661

**FEB 06 2006**

Issued: May 10, 2005

**of Correction**

For: OPTICAL AMPLIFIER WITH PUMP LIGHT SOURCE CONTROL FOR RAMAN AMPLIFICATION

**REQUEST FOR CERTIFICATE OF CORRECTION**

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Feb. 2, 2006

By: H. J. Staas  
H. J. Staas  
Registration No. 22,010

1201 New York Ave, N.W., Suite 700  
Washington, D.C. 20005  
Telephone: (202) 434-1500  
Facsimile: (202) 434-1501

2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO : 6,891,661

DATED : May 10, 2005

INVENTOR(S) : Etsuko HAYASHI, et al.

First Page, Column 2 (Foreign Patent Documents), change "G02F/1/35" to --G02F/135--.

Column 18, line 67, change "In" to --in--.

Column 20, line 50, after "output" delete "power and insert --powers--.

MAILING ADDRESS OF SENDER:  
STAAS & HALSEY LLP  
1201 New York Ave., N.W.  
Suite 700  
Washington, DC 20005

PATENT NO. 6,891,661No. of add'l copies  
@ 50¢ per page

⇒

PCT 2006